

## FRONT END PROGRESS



UPDATE No.:53 - May 2016

(photos KL Collection)



In the past few weeks, No 61662's buffer beam has been rotated 90 degrees, jacked up to the correct height above rail level and given a coat of red paint making it much more presentable to visitors. The smokebox saddle assembly is now on order and the plinth has been extended and reinforced to take the weight of the smokebox. We already have the smokebox door in hand and the composite picture above shows how the front end of the loco will look when the new smokebox is built and the parts are united by the saddle. Funds are urgently needed to complete this phase so please make a donation or buy a share if you can. Thank You.

